



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

April 25, 2007

Supervisor DOZ

Mine Name: Enterprise Millsite
Operator Name: Bonneville Quarries, Inc.

Permit number: S/003/032
Inspection Date: April 11, 2007
Time: 4:00 pm

Inspector(s): Lynn Kunzler, DOGM
Other Participants: none
Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
Routine inspection while in the area.

Inspection Summary:
There was no activity at this site, and apparently has not been any activity for several months (no fresh tracks observed). Most of the rock has been removed from the site. There were two camp trailers, truck trailers and abandoned vehicles as well as a couple piles of debris (ready to be hauled off site. The fuel tank has also been removed from the site. There were no erosional problems noted at this site. The BLM currently holds a bond for this site in the amount of \$11,711.

Photos were taken to document site conditions.

Conclusions and Recommendations:
Operator should be contacted regarding the future of this site. It appears that they may be in the process of reclaiming and closing this site.

Continue to monitor this site when in the area.

Inspector's Signature LK

LK:pb

O:\M003-BoxElder\S0030032-Enterprise\inspections\Insp-04112007.doc